

Flood Risk Management

Section 18 - Schedule

Key Locations and Activities

REF No'	Location and description of works	Remarks
Stewartry		
Kirkcudbright		
SFP 01	Culdoach 3 x screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar
SFP 02	Millburn 3 x screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 03	Kirkhouse – B727 3 x screen clearance & inspection	Checked monthly Apr – Sep, weekly Oct – Mar
SFP 04	Jordieland 2 x screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 05	West of Lochfergus – B727 Screen clearance & inspection	Checked monthly from Apr - Sep, weekly Oct - Mar
SFP 06	Corbie Nest – U53 2 x screen clearance & inspection	Checked monthly Sep, weekly Oct - Mar
Dalbeattie		
SFP 08	Blair Street Screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 09	Maxwell Street 3 x Culvert heads clearance & inspection	Checked monthly from Apr - Sep, weekly Oct – Mar
SFP 10	Galla Crescent & Cemetery Lodge Screen clearance & inspection (9" pipe & ditch)	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 11	Southwick Drive Screen clearance & inspection (grid & gully)	Checked monthly from Apr - Sep, weekly Oct – Mar
SFP 12	Upper Porterbelly Junction – A711 Screen clearance & inspection	Checked monthly from Apr - Oct, weekly Nov – Mar
Castle Douglas		
SFP 13	Abercrombie Industrial Estate Screen clearance & inspection (drainage channels)	Checked monthly from Apr - Sep, weekly Oct – Mar
SFP 14	Dunmuir Road – No' 18 Screen clearance & inspection (9" pipe)	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 15	Ernespie Road/Urr Valley Hotel Screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 16	Oakwell Park/Dalbeattie Road Screen clearance & inspection	Checked monthly from Apr - Sep, weekly Oct – Mar
Gatehouse		

Proposed schedule may be subject to variation dependant on external factors such as site specific constraints, operative safety and extreme weather conditions e.g. drought, storms, snow etc.

SFP 17	Mill Lade 5 x screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 18	Sandgreen C9 at Enrick Screen, cattle grid & 3 x culvert heads clearance & inspection	Checked monthly from Apr - Sep, weekly Oct – Mar
Twynholm		
SFP 19	Coulthard Museum & Nethermain Screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 20	The Doon Screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 21	The Cuil – Langlands Screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
Gelston		
SFP 22	Gelston Burn Watercourse Inspection	Checked annually
Crossmichael		
SFP 23	C46 – Drums Kelly Junction Screen clearance & inspection (9" pipe)	Checked monthly from Apr - Sep, weekly Oct – Mar
Palnackie		
SFP 24	Barwhanny Burn Watercourse inspection	Checked annually
Crocketford		
SFP 25	Crocketford Burn Watercourse inspection	Checked annually
Dundrennan		
SFP 26	Bridge End/Fagra Road Screen clearance & inspection (1 x gully)	Checked monthly from Apr - Sep, weekly Oct – Mar
SFP 27	Abbey View – A711 Screen clearance & inspection (catchpit & 3 x gullies)	Checked monthly from Apr - Sep, weekly Oct – Mar
SFP 28	Port Mary junction – A711/U49 Screen clearance & inspection (2 x catchpit)	Checked monthly from Apr - Sep, weekly Oct – Mar
SFP 29	Port Cheek – U49 Screen clearance & inspection	Checked monthly from Apr - Sep, weekly Oct – Mar
SFP 30	Dundrennan Kirk/Smithy Cottage Screen clearance & inspection	Checked monthly from Apr - Sep, weekly Oct – Mar
Carsphairn		
SFP 31	Green Head Strand Culvert inspection (Bed clearance 15m upstream of culvert)	Checked monthly Nov & Jun
New Galloway		
SFP 32	Navrig Burn Double screen clearance & inspection	Checked monthly Apr – Sep, weekly Dec – Mar & further inspections as conditions dictate.
SFP 33	Public park/Cat Strand	Checked monthly from Apr - Sep,

Proposed schedule may be subject to variation dependant on external factors such as site specific constraints, operative safety and extreme weather conditions e.g. drought, storms, snow etc.

	Screen/culvert clearance & inspection	weekly Oct – Mar
Old Bridge of Urr		
SFP 34	Croys Cottage Screen clearance & inspection	Checked monthly Sep, weekly Oct – Mar
SFP 35	Old Millhouse Screen clearance & inspection	Checked monthly Sep, weekly Oct – Mar
SFP 36	Dubbiedale Mill Screen clearance & inspection	Checked monthly Sep, weekly Oct – Mar
Balmaclellan		
SFP 37	Kenlea Screen clearance & inspection	Checked monthly Sep, weekly Oct – Mar
Auchencairn		
SFP 38	Balliol Court – A711 east of village Screen clearance & inspection	Checked monthly from Apr - Sep, weekly Oct – Mar
Milton		
SFP 39	Barbey – C5 Screen clearance & inspection	Checked monthly from Apr - Sep, weekly Oct – Mar
Borgue		
SFP 40	Tongue Croft Screen clearance & inspection	Checked monthly Nov & Jun
Townhead of Greenlaw		
SFP 41	A713/B795 Screen clearance & inspection	Checked monthly Sep, weekly Oct – Mar
Haugh of Urr		
SFP 42	Redcastle – B794 Screen clearance & inspection	Checked monthly from Apr - Sep, weekly Oct – Mar