

Flood Risk Management

Section 18 - Schedule

Key Locations and Activities

REF No'	Location and description of works	Remarks
Wigtownshire		
Newton Stewart		
WFP 01	Penkiln Burn, Minnigaff Watercourse inspection	Checked annually
Portpatrick		
WFP 02	Enoch reservoir screens and pipe. Screen clearance & inspection.	Checked every 2 months from Apr-Sep, monthly Oct-Mar & further inspections as conditions dictate.
WFP 03	Merrick Reservoir screens, pipe and hydrobrake. Screen clearance and apparatus inspection	Checked monthly from Apr-Sep, weekly Oct-Mar & further inspections as conditions dictate.
WFP 04	Fort Cottage Screen clearance & inspection	Checked monthly from Apr-Sep, weekly Oct-Mar & further inspections as conditions dictate.
WFP 05	Church Walk Wood Screen and secondary screens clearance & inspection	Checked monthly from Apr-Sep, weekly Oct-Mar & further inspections as conditions dictate.
WFP 06	Loreburn Screen clearance & inspection	Checked monthly from Apr-Sep, weekly Oct-Mar & further inspections as conditions dictate.
WFP 07	Church of Scotland Screen clearance & inspection	Checked monthly from Apr-Sep, weekly Oct-Mar & further inspections as conditions dictate.
WFP 24	Hill Street Screen clearance & inspection	Checked monthly Apr-Sep, weekly Oct- Mar & further inspections as conditions dictate.
Glenluce		
WFP 09	St John Street Watercourse & culvert inspection behind houses	Checked monthly Apr-Oct, weekly Nov- Mar & further inspections as conditions dictate.
Creetown		
WFP 10	Minnistone, King George Playing Field. Culvert inlet inspection	Checked Quarterly
WFP 11	Opposite 9 Park Crescent Screen clearance & inspection	Checked Quarterly
WFP 26	Moneypool Burn & Balloch Burn Watercourse inspection	Checked annually
Mochrum		
WFP 12	Opposite No'1 Moat Brae Screen clearance and inspection	Checked monthly from Apr-Nov & weekly Dec-Mar
Kirkcolm		
WFP 14	Behind Bayview Terrace	Checked monthly from Apr-Nov &

Proposed schedule may be subject to variation dependant on external factors such as site specific constraints, operative safety and extreme weather conditions e.g. drought, storms, snow etc.

	Screen clearance & inspection River Level Monitor	weekly Dec-Mar. Debris cleared from burn as conditions dictate.
Port Logan		
WFP 15	At Septic tank and seaward side of main street. Screen clearance and inspection NRV inspection	Checked monthly from Apr-Oct, weekly Dec-Mar & further inspections as conditions dictate. Debris cleared from burn as conditions dictate.
Stranraer		
WFP 16	Station Street, Town Burn at NFU building. Screen clearance and inspection	Checked monthly Apr-Oct & weekly Nov-Mar
WFP 17	Auchtralure Farm road behind Thornycroft Care Home. Screen clearance and silt trap clearance.	Checked monthly Apr-Oct & weekly Nov-Mar
WFP 18	Sheuchan Burn, The Grove Screen clearance & inspection River Level Monitor	Checked monthly Apr-Oct & weekly Nov-Mar
WFP 19	Gallowhill Rise, Storm drain Screen clearance & inspection	Checked monthly Apr-Mar. Silt traps cleaned as conditions dictate.
WFP 20	Jackies Loaning Screen clearance & inspection	Checked monthly Apr-Oct, weekly Nov-Mar & further inspections as conditions dictate.
WFP 21	Dalrymple Street cemetery Screen clearance & inspection	Checked monthly Apr-Oct & weekly Nov-Mar
Leswalt		
WFP 23	Behind play park Screen clearance & inspection	Checked monthly Apr-Nov & weekly Dec-Mar
Port William		
WFP 25	Second Sands Screen clearance & inspection	Checked monthly Apr-Sep, weekly Oct-Mar & further inspections as conditions dictate.